# WOW2 Walk Over Weigh Scale Indicator



# Monitor weight trends with hands free Walk Over Weighing.

Use weight trends to identify poor performers, optimise breeding programmes and catch animal health issues early. Developed for the harsh dairy environment and applications where cattle are regularly weighed.

The Tru-Test WOW2 Walk Over Weigh Scale Indicator is designed to be integrated with third party management software capable of interpreting and analysing data.

Regularly recording individual weights against EID tags enables you to monitor weights, trends and changes to back up your crucial animal management decisions.

Identifying weight trends can assist you in identifying sick or lame animals early, adjust feed to extend peak milk, minimise treatment waste and monitor animal condition for breeding success.

Integrated weighing in the shed's exit race means weights are captured at every milking for constant performance monitoring. Walk Over Weighing allows you to weigh animals without stopping them on the platform.

- EID compatible.
- ✓ Stores up to 100 weighing sessions and 30.000 animal records.
- Capture weight without stopping animal
- Auto zero functionality.
- Water, dust and shock proof IP67 case.
- Integrate with third party software by either streaming data or recording information on the weigh scale to download later.

How are you tracking? Let's talk. 1800 641 324 (AU)



### FEATURES AND SPECIFICATIONS

### · Record what you need

Capacity to store up to 100 weighing sessions and 30,000 animal records. Integrate with third party software by either streaming data or recording information on the weigh scale to download later.

### Accurate weight trends

90% of animal weights are captured with an accuracy of ±3% when using the weekly average of each animal's processed daily recordings. Third party management software should be used to filter out any incorrectly captured data to build up statistically accurate weight trends over time.

### Autozero

Any dirt or muck build up on the platform is automatically zeroed out.

### Built tough

Ideal for use in a dairy shed environment or anywhere cattle are regularly weighed. Water, shock and dust proof IP67 case with a durable double walled case construction.

### · Plug and play load cell connection

Plug and play load cell connection. Compatible with all load sensors in the Tru-Test range, no calibration required.

### • Bluetooth®wireless interface

Reduce cables by using *Bluetooth* to connect to the EID reader or third party management system.

### Power

In typical walk-over weighing applications the weigh scale indicator is permanently connected to an external power source. Internal battery run time of 15 hours.

### Information transfer

Quickly transfer information through your (Android\*) mobile device or computer (Microsoft Windows\*).

### Size-WxHxD

205 mm x 220 mm x 74 mm (8" x 9½" x 3")

# Weight

 $1.1 \text{ kg} (2 \frac{1}{2} \text{ lb})$ 

# **ORDER INFORMATION**

### **WOW2 Weigh Scale Indicator**

Includes: Mains power adaptor (with pin plates), mounting bracket kit, adaptor cable for serial and power, serial cable, serial to USB converter cable, USB flash drive.

Part No: 828996

Although the information presented in this Product Information Sheet is believed to be accurate and reliable, no responsibility for inaccuracies can be assumed by Tru-Test Limited. Performance data is typical only and variations due to component manufacturing tolerances are normal. Tru-Test Limited reserves the right at any time to change performance characteristics or specifications without prior notice. All trade marks with an \* are not owned by Tru-Test and belong to their respective owners. © Tru-Test Limited 2013 - All rights reserved.

The Bluetooth\* word mark and logos are owned by Bluetooth SIG, Inc. and any use of such marks by Tru-Test Limited is under licence.

2344TTSMO2 Issue 2 11/15

How are you tracking? Let's talk. 1800 641 324 (AU)